

EAST Search History

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|-------|------|---|---|------------------|---------|------------------|
| L1 | 269 | 384/295.ccls. | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT | OR | OFF | 2006/08/30 11:14 |
| L2 | 4 | ("1361471").URPN. | USPAT | OR | OFF | 2006/08/30 11:08 |
| L3 | 809 | 384/276.ccls. | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT | OR | OFF | 2006/08/30 11:14 |
| L4 | 2136 | bushing with split and (spiral or helical or angle\$1 or diagonal) | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT | OR | OFF | 2006/08/30 11:39 |
| L5 | 772 | split near bushing and (spiral or helical or angle\$1 or diagonal) | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT | OR | OFF | 2006/08/30 11:40 |
| L6 | 140 | 384/273 | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT | OR | OFF | 2006/08/30 13:56 |
| L7 | 164 | 384/273.ccls. | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT | OR | OFF | 2006/08/30 14:03 |
| L8 | 3 | ("1552054").URPN. | USPAT | OR | OFF | 2006/08/30 14:00 |
| L9 | 17 | 384/211.ccls. | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT | OR | OFF | 2006/08/30 14:03 |
| L10 | 14 | (US-4913562-\$ or US-3033623-\$ or US-5880043-\$ or US-5145265-\$ or US-1361471-\$ or US-4764035-\$ or US-4878766-\$ or US-1158862-\$ or US-4047771-\$ or US-6116573-\$ or US-6209183-\$ or US-1395946-\$).did. or (US-1129116-\$ or US-1552054-\$). did. | USPAT; USOCR | OR | OFF | 2006/08/30 14:11 |
| L11 | 1 | 10 and (pvc or polyvinyl chloride) | USPAT; USOCR | OR | OFF | 2006/08/30 14:54 |

EAST Search History

| | | | | | | |
|-----|------|--|------------------------------|----|-----|------------------|
| L12 | 6 | 10 and plastic | USPAT; USOCR | OR | OFF | 2006/08/30 14:13 |
| L13 | 1076 | (384/271,272,280,281,428,212).CCLS. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/30 14:13 |
| L14 | 1009 | (267/279,281,282,293).CCLS. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/30 14:13 |
| L15 | 0 | 10 and (pvc or polyvinyl with chloride) | USPAT; USOCR | OR | OFF | 2006/08/30 14:58 |
| L16 | 1826 | bushing and (PVC or Polyvinyl adj chloride) | USPAT; USOCR | OR | OFF | 2006/08/30 14:59 |
| L17 | 70 | bushing near4 (PVC or Polyvinyl adj chloride) | USPAT; USOCR | OR | OFF | 2006/08/30 15:01 |
| L18 | 128 | bushing with (PVC or Polyvinyl adj chloride) | USPAT; USOCR | OR | OFF | 2006/08/30 15:02 |
| L19 | 58 | 18 not 17 | USPAT; USOCR | OR | OFF | 2006/08/30 15:02 |
| S1 | 25 | (384/301).CCLS. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:14 |
| S2 | 28 | ("2815253" "2851314" "2964341" "3008779" "3033623" "4509870" "4603982" "4765757" "4767677" "D143258" "D227397").PN. OR ("4913562").URPN. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:16 |
| S3 | 24 | ("1849963" "2675283" "3033623" "3438686" "4624585" "4913562").PN. OR ("5145265").URPN. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:18 |
| S4 | 721 | 384/297.ccls. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:33 |
| S5 | 72 | bushing and (radial or helical) near split | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:33 |
| S6 | 0 | ("2005/0207686").URPN. | USPAT | OR | OFF | 2006/08/29 15:36 |
| S7 | 71 | 384/299.ccls. | USPAT | OR | OFF | 2006/08/29 15:37 |
| S8 | 16 | ("3033623").URPN. | USPAT | OR | OFF | 2006/08/29 15:42 |
| S9 | 192 | 384/300.ccls. | USPAT | OR | OFF | 2006/08/29 15:42 |
| S10 | 3 | ("3684062" "4674164").PN. OR ("5880043").URPN. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:47 |
| S11 | 131 | 380/275.ccls. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:47 |

EAST Search History

| | | | | | | |
|-----|-----|---------------|------------------------------|----|-----|------------------|
| S12 | 179 | 384/275.ccls. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:54 |
| S13 | 291 | 384/296.ccls. | US-PGPUB; USPAT; USOCR | OR | OFF | 2006/08/29 15:54 |